

LATEST VEHICLE CONCERN FIXES

ELECTRICAL



L551 IDMA Flickers/Scrolls	19 - 20MY RR Evoque L551
<p>Customer Voice:</p> <ul style="list-style-type: none">• Upper and/or Lower screen flickering/ jitter behavior <p>Technical Description:</p> <ul style="list-style-type: none">• APIX cable length are not compatible with APIX tuning parameters in IDMA, ICDM, and IMC. <p>Status:</p> <ul style="list-style-type: none">• Parameter change to be released with 20B software release• 20B software release via SOTA on July 15th• If a vehicle had a APIX cable replaced to resolve this issue it may need to return after 20B software update.	

