



SERVICE BULLETIN

Classification: EL20-022	Reference: NTB20-047	Date: July 6, 2020
-----------------------------	-------------------------	-----------------------

2020 ROGUE; HIGH HORN ASSEMBLY AND HORN RELAY

APPLIED VEHICLE: 2020 Rogue (T32)
APPLIED VIN AND DATE: VIN starting with **5N1** and built after January 31, 2020

SERVICE INFORMATION

The high horn assembly and horn relay are no longer installed from the factory. These components have been intentionally decontented, are not missing and should not be installed.

- Warranty claims for installing these components will be denied.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 6, 2020	NTB20-047	Original bulletin published

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.