

Service Bulletin

Bulletin No.: 20-NA-064

Date: June, 2020

TECHNICAL

Subject: Wind and/or White/Static Type Noise Heard Near Transmission Shifter

Brand:	Model:	Model Year:		Breakpoint:		Engino	Transmission:
		from	to	from	to	Engine:	
Chevrolet							Equipped with 6
Holden	Equinox	2019	2020	-	-	-	SPD Automatic Transmission (RPOs MNH, MNK)

Involved Region or Country	United States, Canada, Mexico, Middle East, Israel, Palestine, Argentina (Mercosur), Brazil (Mercosur), Chile (West), Colombia (West), Ecuador (West), Paraguay (West), Peru (West), Uruguay (West), GM Korea Company, Thailand (ASEAN), Australia/New Zealand, Egypt, Other Africa	
Condition	Some customers may comment on a wind and/or white/static type noise heard near the transmission shifter.	
Cause	This condition may be caused by the transmission harmonics traveling through the transmission range selector cable, causing noise.	
Correction	Replace the transmission range selector cable. Refer to Range Selector Lever Cable Replacement in SI.	

Parts Information

Causal Part	Description	Part Number	Qty
Х	CABLE ASM-A/ TRNS RANGE SEL LVR	84835018	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8460370	Range Selector Lever Cable Replacement	Use Published Labor Operation Time

Version	1
Modified	Released June 04, 2020

