

Subject: Engineering Information - Shift to Park Message On the Drivers Information Center (DIC) (ONLY On Push Button Ignition), Unable to Remove Key from Ignition Cylinder and/or Difficult to Shift Out of Park

This PI has been revised to end the need for information from the field. Please discard PIE0568B.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2019	-	-	-	-
	Silverado 2500HD/3500HD	2020	2020				
	Silverado 1500	2020	2020				
GMC	Sierra 1500 (New Model)	2019	2019				
	Sierra 2500HD/3500HD	2020	2020				
	Sierra 1500	2020	2020				

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	4
Modified	<p>Release May 11, 2020</p> <p>Revised May 12, 2020 – Updated to add Silverado 2500HD/3500HD and Sierra 2500HD/3500HD.</p> <p>Revised May 26, 2020 – Updated information under the Correction.</p> <p>Revised June 10, 2020 – Ended the need for further information from the field.</p>