



Preliminary Information

PIT5689B No Restart after an Auto Stop Event / No Crank / DTC U0102 U0284 U0285 U0672 P0617 P26E6 P305D U111A U111E U1348

Product Investigation Review Required

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
Chevrolet	Silverado 1500	2020	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500	2020	All	All	All	All

Involved Region or Country	North America
Condition	<p>Some customers may comment of the following:</p> <ul style="list-style-type: none"> - After an auto-stop event the engine does not restart. - No crank (may be intermittent) - SES MIL with any of the following DTCs: U0102, U0284, U0285, U0672, P0617, P26E6, P305D, U111A, U111E, U1348
Cause	These concerns are currently being reviewed under engineering investigation PIE0572. Please review PIE0572 if vehicle is exhibiting these conditions.

Version History

Version	3
Modified	<p>06/04/2019 - Created on</p> <p>11/22/2019 - superseded to update the title, condition and correction.</p> <p>6/22/2020 - Updated to temporarily refer to PIE0572 for this condition.</p>



GENERAL MOTORS

© 2020 General Motors. All Rights Reserved.