


Preliminary Information

PIC6418 Navigation Loading Message And Navigation Won't Start or Slow to Start When Ignition Is First Turned On

Models

Brand:	Model:	Model Years:	VIN:		Engine	Turumusiasiama
			from	to	Engine:	Transmissions:
Buick	Regal	2018 - 2020	All	All	All	All
Cadillac	ATS	2018 - 2019	All	All	All	All
Cadillac	стѕ	2018 - 2019	All	All	All	All
Cadillac	XTS	2018 - 2019	All	All	All	All
GMC	Terrain	2018	All	All	All	All
Holden	Commodore	2018 - 2020	All	All	All	All



Correction:

: Verify condition is as described and recovers with the work around method.

Service Procedure

Reproduce the condition at ignition on/engine start. Verify the condition is present, then perform the following steps:

Go to Home screen > Settings > System > Running Applications



Select the "Stop" button on the "Navigation" application line, then select OK. This will force the application to restart.





Launch navigation from the Home page.

If the navigation still will not launch, then this PI does not apply. Refer to SI for diagnostic procedures.

If the navigation recovers for that ignition cycle, then please explain to the customer that engineering is investigating this condition. This PI will be revised or replaced with a bulletin once a root cause is identified.

Parts Information

Do not replace any parts for this condition.

Warranty Information

Labor Operation	Description	Labor Time			
3487088*	Confirm Navigation Loading Condition	.3			
*This is a unique Labor Operation for Bulletin use only.					

Version	1
Modified	7/16/2020 - Created

















GENERAL MOTORS

 $\hbox{@ 2020 General Motors.}$ All Rights Reserved.