

Bulletin No.: PIT5758A Published date: 07/30/2020

Preliminary Information

PIT5758A Unwanted or False Front Park Assist Alerts

<u>Models</u>

| Brand: | Model: | | Model Years: | VIN: | | Engine | Transmissions: | |
|----------------------------|--------------|--|--------------|------|-----|---------|----------------|--|
| Dranu. | | | | from | to | Engine: | Transmissions. | |
| GMC | Yukon Models | | 2021 | All | All | All | All | |
| Involved Region or Country | | North America | | | | | | |
| Additional Options (RPO) | | UD5 | | | | | | |
| Condition | | Some customers may comment on unwanted/false front park assist alerts. These false alerts generally indicate an object being on the far left, far right or both, as shown below. | | | | | | |
| Cause | | This concern could be caused by an issue with the K182 Parking Assist Control Module software. | | | | | | |



Correction:

If you experience the concern above, please update the software in the K182 Parking Assist Control Module with the latest software available in TIS-2-Web

Version History

| Version | 2 |
|----------|---|
| | 07/10/2020 - Created on. |
| Modified | 07/30/2020 - PI updated for software update which is now available. |
| | |



© 2020 General Motors. All Rights Reserved.