On-car analysis list from August 3rd, 2020 please contact VW Helpline before attempting repair

	Models	MY	Engine	Transmission	Topic	Customer Complaint
Powertrain	Jetta	19-20	1.4T	All	MIL-on P0496	Customer states MIL-on
			(DGXA / DJXA)			(Must have P0496 in the ECM) Customer states MIL-on
	Jetta	19-20	1.4T	All	MIL-on U0284	(Must have U0284 in the ECM)
			(DGXA / DJXA)			(untouched vehicles)
	Atlas, Atlas Cross	19-21	3.6L	All	Engine Oil Leak	Customer states engine oil leak (leaking from cylinder head valve cover ONLY)
	Sport	19-21	(CDVC)	All	Erigine Oil Leak	(untouched vehicles)
	Jetta, Golf,		1.4T			Customer states engine oil leak
	SportWagen	19-20	(DGXA / DJXA)	All	Engine Oil Leak	(UPPER or LOWER ENGINE OIL PAN ONLY)
	.,		(- , - ,			(untouched vehicles) Customer states MIL-on
	Jetta	18-19	1.4T	All	MIL-on P0111	(Must have P0111 in the ECM)
			(CZTA, DGXA, DJXA)			(untouched vehicles)
	Atlas, Atlas Cross		3.6L			Customer states MIL-on
۵	Sport	18-21	(CDVC)	All	MIL-on P2407	(Must have P2407 in the ECM) (For MY18 & MY19, software must be level 9970 or higher)
						(FOI WITE & WITE, SOILWARE HILLS)
						Customer states MIL-on
	Tiguan	20	2.0T	All	MIL-on P11**	(Must have P11A1/P11A2/P11A3/P11A4/P11A5/P11A6/P11A7/P11A8/
	Ü		(DGUA)			P11A9/P11AA/P11AB/P11AC/P11AD/P11AE/P11AF/P11B0 in the ECM) (Untouched vehicles)
						(Ontouched vehicles)
	Jetta GLI	19-20	2.0T	All	Fuel Line Rattle	Customer states rattle noise from under vehicle
	Jetta GLI, Golf GTI,		(DKFA) 2.0T			(Must confirm fuel lines are source of noise) Customer states MIL-on, HPFP mounting bolts loose/broken
	Tiguan	19	(DKFA, DGUA)	All	HPFP Bolt	(HPFP bolts must be loose/broken)
_						
	Passat	19-20	All	All	No Terminal 15	Customer states "No Crank/No Start"
	Passat	19-20	All	All	NO Terminal 15	(untouched vehicles)
ica						
Electrical		46.00				Driver seat heater inoperative
	Passat	16-20	All	All	Seat Heater	(Must have fault code B139813 in A/C/heating electronics) (untouched vehicles)
						Customer states both headlights are cracked
	Jetta	19	All	All	Headlights cracked	(untouched vehicles)
						(CANNOT have outside influence)
Body	Atlas	19-20	All	All	Dash Noise	Customer states noise heard when adjusting air distribution on HVAC controls
	7.003	13 20	, ai	, (1)	243110130	(untouched vehicles)
						Wind Noise from the Front Driver or Passenger Door
	Atlas	19-20	All	All	Wind Nosie	(untouched vehicles)
	1-44- 1					(CANNOT have outside influence)
Other	Jetta, Jetta Wagon, Jetta					Customer states MIL-on
	SportWagen, Golf,		2.0 TDI			(Must have P0401 in the ECM)
	Golf Wagon,	09-14	(CJAA/CBEA)	All	TB Data P0401	(Must be performing TB 01-18-13 / 2034898)
	Beetle, Beetle					(concern group TDI Emissions) (Fill out attachment in VTA: Gen I-TDI Survey)
	Convertible					m out attachment in VIA. Gen i-151 SuiVey