

Technical Service Bulletin

93 MIL on, DTC logged for the HV battery (GFF indicates that the battery should be replaced)

93 20 32 2049384/3 August 5, 2020. Supersedes Technical Service Bulletin Group 93 number 19-11 dated April 24, 2019 for reasons listed below.

| Model(s) | Year | VIN Range | Vehicle-Specific Equipment |
|------------------------|-------------|-----------|----------------------------|
| А3 | 2016 - 2018 | All | e-tron |
| Audi e-tron quattro | 2019 - 2020 | All | e-tron |
| A8, Q5 | 2020 | All | PHEV |

Condition

| REVISION HISTORY | | | | |
|------------------|------------|--|--|--|
| Revision | Date | Purpose | | |
| 3 | - | Revised header (Added A8 and Q5) | | |
| 2 | 04/24/2019 | Revised header (Updated documentation, added model years, and model) | | |
| 1 | 11/16/2017 | Initial publication | | |

Customer may report:

MIL on.

Workshop findings:

- In the battery regulation control module, J840 (address word 008C) or in the high-voltage battery charger control module, J1050 (address word 00C6) a DTC is logged for the HV battery.
- GFF is performed and indicates to replace the HV battery.

Technical Background

Not applicable.

Production Solution

Not applicable.



Technical Service Bulletin

Service

- 1. Review and follow the instructions in the **attached document** to ensure correct documentation is performed for any battery repairs.
- 2. Perform classification test plan to determine the state of the battery, for shipping process (critical or non-critical).
- 3. Contact TAC with requested documentation uploaded.
- 4. Complete the attached document after TAC provides direction.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All parts and service references provided in this TSB (2049384) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.