



Technical Journal

TITLE:

Illumination of cup holder in center console, missingREF NO:
TJ 35594.1.0ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2020-07-10STATUS DATE:
2020-07-15FUNC GROUP:
8825FUNC DESC:
Storage basket; storage tray;
storage sh

Page 1 of 1

“Right first time in Time”

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
246							2021-2021	21	0670087-0999999	202024-202037
246							2021-2021	36	0672492-0999999	202023-202037
256							2021-2021		0670061-0999999	202024-202037

CSC Customer Symptom Codes

Code	Description
VV	Center console/Cup holder problems

DESCRIPTION:

A number of cars have been built without wiring for the illumination in the cup holders in the center console.

These cars have VDN code PD03 and are in the range described under “Vehicle Type”.

Do NOT try to rebuild these cars to a working illumination.

SERVICE:

Warranty claim info:

No warranty claim accepted for a job described in this TJ

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 8825.