

Message in the Instrument Cluster "Refill 1L Oil at the Next Fuel Stop"

Topic number	LI18.40-P-070746
Version	3
Function group	18.40 Oil level/oil pressure sensor
Date	07-02-2020
Validity	Model Year 2019+ 205 with M177 Engine
Reason for change	Corrected MY range
Reason for block	

Complaint:

Message in the Instrument Cluster "Refill 1L Oil at the Next Fuel Stop"

Cause:

PTCU Software

Remedy:

Update the PTCU software.

Check oil level and correct if necessary.

Symptoms
Power generation / Engine lubrication/oil cooling / Indicator lamp / Engine oil level indicator lamp / lit
Power generation / Engine lubrication/oil cooling / Display message / Oil sensor message

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			5440Z 90	