

Rear spoiler chatters/vibrates

Topic number	LI88.30-P-071543
Version	1
Function group	88.30 Detachable components, underride guard
Date	07-28-2020
Validity	BR X290 (without code U94 and without code U99) with manufacturing date up to and including July 6 2020
Reason for change	
Reason for block	

Complaint:

Rear spoiler chatters/vibrates when extending/retracting, see video in attachment.

Attachments	
File	Description
Spoiler_Rattern.mp4	Rear spoiler chatters/vibrates

Cause:

Possible drive mechanism irregularity.

Remedy:

Replace rear spoiler drive unit.

In the event of complaints after a production date of July 6 2020, a PTSS case must be created.

Note:

In the event of complaints about other noises from the rear spoiler (such as a "thunk" after closing the spoiler), replacing the drive unit is not an effective solution, or may not be a permanently effective solution. If there is any doubt, create a PTSS case.

Symptoms
Body / Body/Cab / Spoiler / Operation, noises

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 290 790 00 00			Rear spoiler kinematics system with electric motor	1		X

WIS-References

XENTRY TIPS

Document number	Title	Note	Allocation
ar88.30-p-0509frx	Remove/install rear wing		Remedy