



SERVICE BULLETIN

July, 2020

Subject: **Repair Procedure Revision- Brake Light
Switch Adjustment**No. **2020-6**


SERVICE INFORMATION

YEAR	MODEL
2020 and newer	Spyder RT

Vehicles may indicate brake light switch failure. One of the probable cause is the adjustment of the brake light switch / low pressure switch.

BUDS2 will return one or more of the following codes:

- C0040 - Brake light switch failure
- P061E - Brake signal state Invalid
- P0504 - Brake signal not plausible
- C0042 - Low brake pressure switch
- C1182 - Brake failure (low pressure switch)



PROCEDURE

Refer to the following procedures.

- **Task:** *INSPECTING THE ADJUSTMENT OF THE BRAKE LIGHT SWITCH / LOW PRESSURE SWITCH (BLS/LPS).*
- **Task:** *ADJUSTING THE BRAKE LIGHT SWITCH / LOW PRESSURE SWITCH (BLS/LPS).*

Always refer to the appropriate *ONLINE REPAIR MANUAL* for the latest informations and procedures.