

Service Bulletin

Bulletin No.: 20-NA-079

Date: July, 2020

TECHNICAL

Subject: Front Brake Squeal Noise Heard During Light Brake Pedal Application

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to	Engine.	Transinission.
Buick	Encore GX	2020	2020	SOP	March 20, 2020	All	All

Involved Region or Country	North America Only	
Condition	Some customers may comment on hearing a squeal noise originating from the front of the vehicle during light brake pedal application.	
Cause	The squeal noise can occur during light brake pedal application at low vehicle speed when the brakes are first applied or lightly applied. Occasionally this noise may appear from the front, while in Reverse, after a period of non-use such as overnight, or cold brakes and/or in high humidity conditions.	
Correction	Replace the front brake pad kit with shims that have been released to correct this condition.	

Service Procedure

If you encounter a vehicle with the above concern, replace the front brake pads and sensor. Refer to *Front Disc Brake Pads Replacement* in SI.

Parts Information

Causal Part	Description	Part Number	Qty
Х	PAD KIT, FRT DISC BRK	42747910	1
_	FRT DISC BRK PAD WEAR SENSOR	42726383	1

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2420150	Front Disc Brake Pads Replacement	Use Published Labor Operation Time

Version	1
Modified	Released July 16, 2020