

**SSM 49120 - 2020 Aviator - 3.0L Hybrid - Illuminated MIL With DTC P0BCD -
Built On Or Before 18-Jul-2020**

Some 2020 Aviator vehicles equipped with a 3.0L hybrid engine and built on or before 18-Jul-2020 may exhibit an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P0BCD stored in the inverter system controller (SOBDMC). This may be due to the software in the SOBDMC. To correct the condition, reprogram the SOBDMC with the latest software level of the appropriate Ford diagnostic scan tool. For claiming, use causal part 7B012 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES
2020 CAR: TV U611N AVIATOR