

SSM 49121 - 2020 Escape/Corsair - Roof Opening Panel - Flutter, Hum, And/Or Wind Noise While Driving

Some 2020 Escape/Corsair vehicles equipped with a roof opening panel may exhibit a flutter, hum, and/or wind noise while driving. This may be due to an incorrectly adjusted roof opening panel. Components should not be replaced for this condition. Adjust the roof opening panel so that the front edge of the sliding glass panel is contacting the margin seal. Refer to Workshop Manual (WSM), Section 501-17. After adjustment perform a power roof opening panel initialization. Refer to WSM, Section 501-17.

APPLICABLE VEHICLES

2020 CAR: TC CX482N ESCAPE

2020 CAR: TF CX483N CORSAIR