



SPYDER Pressurized Crankcase On 1330 Engines - 137963

[Printable Version](#)

Rate This Article

(Average Rating: No Rating)

[Version 1](#)Language English ▼[Show Properties](#)**Summary:**

The engine crankcase might be pressurized because of blocked breather hose.


Type:

General

TST Detail:**Problem:**

The engine might leak prematurely and pressure release can be noticed when removing the oil dipstick.

Solution:



Inspection Procedure:

Inspect the intake inlet at the throttle body. The breather hose inlet might be blocked not allowing crankcase to breathe and creating internal engine pressure.

If the hole is blocked, simply open it by using a small blade.

Warranty:

Normal warranty applies

Attachment:

First Published By: Eric Fauteux on 2020-08-27

Last Modified By: Eric Fauteux on 2020-08-27