

# Technical product information

<b>Topic</b>	Bentayga - Ticking noise behind Driver Instrument Panel
<b>Market area</b>	Bentley: worldwide (2WBE),Hongkong-Macau (5HK)
<b>Brand</b>	Bentley
<b>Transaction No.</b>	2054077/3
<b>Level</b>	EH
<b>Status</b>	Approval
<b>Release date</b>	

## New customer code

Object of complaint	Complaint type	Position
engine -> induction system, charging systems, vacuum systems	noise, vibration	

## New workshop code

Object of complaint	Complaint type	Position
engine -> induction system, charging systems, vacuum systems -> central feed vacuum pump	noise, vibration -> noise	

# Vehicle data

## Bentayga series

### Sales types

Type	MY	Brand	Designation	Engine code	Gearbox code	Final drive code
4V1*	2017	E		*	*	*
4V1*	2018	E		*	*	*
4V1*	2019	E		*	*	*
4V1*	2020	E		*	*	*
4V1*	2021	E		*	*	*

# Documents

Document name
<a href="#">master.xml</a>

## Bentayga - Ticking noise behind Driver Instrument Panel

## Customer statement / workshop findings

Ticking noise behind the Driver Instrument Panel.

## Technical background

In certain circumstances a ticking noise behind the Driver Instrument Panel may be audible within the vehicle cabin. The ticking noise emanates from the vacuum system and may be more noticeable following several successive brake pedal actuations.

Refer to the video on the Bentley Hub referencing TPI 2054077/3

If the complaint noise is as shown in the video, the customer should be advised that this is normal and does not represent a failure or malfunction on the vehicle

## Production change

## Measure

No applicable