

CAMPAIGN LAUNCH STATUS

DEFENDER SERVICE ACTION N472



SERVICE ACTION N472 – A POST WIND NOISE	
AFFECTED MODELS	20MY DEFENDER
VOLUME AFFECTED	1125 USA
REPAIR	Fix is required to remove risk of a 'tapping' type of wind noise at the A post. The A post trim to be removed and felt tape applied to the trim mounting clips to increase clearance to the body.
REPAIR TIME	0.2hrs + drive in/out
TARGET CAMPAIGN LAUNCH	August 3 rd 2020
Notes	*Care required in removing lower bolt covers as replacement parts are not yet available. Also requires locally sourced felt tape.

