

# CAMPAIGN LAUNCH STATUS

## DEFENDER SERVICE ACTION - N472



SERVICE ACTION N472 – A POST WIND NOISE	
AFFECTED MODELS	20MY DEFENDER
VOLUME AFFECTED	1125 USA 217 CANADA
REPAIR	Fix is required to remove risk of a 'tapping' type of wind noise at the A post. The A post trim to be removed and felt tape applied to the trim mounting clips to increase clearance to the body.
REPAIR TIME	0.2hrs + drive in/out
CAMPAIGN LAUNCHED	August 4 <sup>th</sup> 2020
Notes	*Care required in removing lower bolt covers as replacement parts are not yet available. Also requires locally sourced felt tape.

