

CAMPAIGN LAUNCH STATUS

SERVICE ACTION N480 AND UPDATE PRIOR TO SALE N444



| SERVICE ACTION N480 – ROOF WATER INGRESS | | UPS N444 – SUNBLIND APERTURE SEAL | |
|--|---|-----------------------------------|---|
| AFFECTED MODEL | RANGE ROVER VELAR 20MY | AFFECTED MODEL | DISCOVERY 17-20MY |
| VOLUME AFFECTED | 128 USA 21 CANADA | VOLUME AFFECTED | 396 USA 29 CANADA |
| REPAIR | To prevent water ingress from RH A post & headliner, apply sealant between roof cassette and roof panel | REPAIR | To prevent the panoramic roof blind from jamming, 4 clips are to installed on the aperture seal |
| REPAIR TIME | 0.3 hrs + Drive in/out | REPAIR TIME | 0.2 hrs + Drive in/out |
| CAMPAIGN LAUNCH | August 11 th 2020 | CAMPAIGN LAUNCH | August 11 th 2020 |
| Notes | Repair prior to sale and for sold vehicles at next service visit | Notes | Population are all unsold units. Repair to be performed prior to sale |