

## TECHNICAL TOPICS ELECTRICAL



### L551 Glitching Screen

### 20MY RR Evoque

#### Customer Voice:

- Upper and/or Lower screen behaves erratically: glitching, flickering, or scrolling.

#### Technical Description:

- A software calibration change was released in 20B1, some vehicles continue to exhibit erratic behavior.

#### Status:

- If the issue persists after installing 20B1 lock the vehicle and allow it to go to sleep.
- If the issue continues, check the APIX cables for proper routing, any damage, kinks, or tight bends.
- For any issues that are discovered post 20B1 please submit a TA or EPQR with photos of the failure mode and the IMC is already at 20B1.

