

## TECHNICAL TOPICS POWERTRAIN



### Tip-in Hesitation

19/20 MY Range Rover, RR Sport, Defender equipped with AJ20P6

#### Customer Voice:

- There is a delay when accelerating.

#### Technical Description:

- A tip-in hesitation is identified and resolved with replacement of the upstream (B1S1) oxygen sensor.
- It is possible no DTCs are stored.

#### Status:

- Raise an EPQR if replacement of the O2 sensor resolves the customer complaint.
- Include a session file (even if no DTC is stored) and contact information (name, email address, phone number) for someone at the retailer who can serve as the point of contact for PRR.

