

TECHNICAL TOPICS

BODY



Rear Roof Blind Aperture Seal Adrift

17 – 20MY Discovery

Customer Voice:

- A customer may report that the rear roof blind seal is coming loose or that the power rear roof blind is not operating properly.

Technical Description:

- On certain Discovery model variants the rear roof blind seal may be coming loose due to poor retention.

Status:

- New retaining clips have been developed to address this concern.
- Service Action N444 is being published to proactively address this concern by removing the blind seal and installing new retaining clips to keep the seal in place.

