

TECHNICAL TOPICS

BODY



Rear Doors Difficult To Open

20MY Defender

Customer Voice:

- A customer may report the rear door is difficult to open.

Technical Description:

- The rear door seal may catch and drag on the quarter glass due to an incorrect C-Pillar exterior trim finisher alignment.

Status:

- SSM74962 was published July 29, 2020 to initially address this concern.
- TSB JLRTB02052NAS1 is being published to replace SSM74962.
- Should a customer express a concern, please refer to this TSB for repair guidance.

