


TECHNICAL TOPICS

BODY



Tailgate Mounted Tail Lamp Condensation / Water Ingress	20-21 MY RR Evoque
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• A customer may report that the rear tailgate tail lamp has moisture in it. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• A tailgate mounted tail lamp may develop condensation or standing water in the lamp housing. <p><u>Status:</u></p> <ul style="list-style-type: none">• Engineering is currently investigating this concern.• Please submit an EPQR with pictures for any tailgate tail lamps you find with this concern.• A request for return of any failed parts will be raised to support the investigation.	 <p>The tailgate tail lamp as shown.</p>

