## Subject: Engineering Information – Malfunction Indicator Lamp (MIL) Illuminated and/or Functional Failures of the Airflow Shutter, DTCs P05AE, U0284, P059F, U0285 Set

## This PI has been revised to end the need for information from the field. Please discard PIE0566.

| Brand:    | Model:                        | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|-------------------------------|-------------|------|------|----|---------|---------------|
|           |                               | from        | to   | from | to |         |               |
| Chevrolet | Silverado 1500 (New<br>Model) | 2019        | 2020 | -    | -  | -       | -             |
| GMC       | Sierra 1500 (New Model)       |             |      |      |    |         |               |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| Version  | 2   |  |
|----------|---|--|
| Modified | Released May 01, 2020<br>Revised July 08, 2020 – Ended the need for further information from the field. |  |