

Subject: Engineering Information – SD Card Error Code and Message Displayed on Radio Screen and/or Instrument Cluster - Navigation System Malfunction

This PI has been revised to end the need for information from the field. Please discard PIE0567.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Buick | Enclave | 2020 | 2020 | - | - | - | - |
| | Encore GX | | | | | | |
| Cadillac | XT4 | | | | | | |
| | XT5 | | | | | | |
| | XT6 | | | | | | |
| Chevrolet | Blazer | | | | | | |
| | Camaro | | | | | | |
| | Silverado 1500 | | | | | | |
| | Traverse | | | | | | |
| GMC | Acadia | | | | | | |
| | Sierra 1500 | | | | | | |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| | |
|-----------------|---|
| Version | 2 |
| Modified | Released May 04, 2020 June 30, 2020 – Ended the need for further information from the field. |