

**Subject: Engineering Information - Torque Converter Clutch (TCC) Shudder Occurring On Light Throttle Acceleration 2-6 Gears**

*This PI has been revised to end the need for information from the field. Please discard PIE0570.*

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2020	2020	-	-	-	Equipped with 9 SPD Transmission (RPO M3W)
Chevrolet	Traverse						Equipped with 9 SPD Transmission (RPO M3V)

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

<b>Version</b>	2
<b>Modified</b>	Released May 21, 2020 Revised July 22, 2020 – Ended the need for further information from the field.