



Reference:

ITB98-036b

Date:

August 5, 2020

## VOLUNTARY SERVICE CAMPAIGN 1996 I30 MALFUNCTION INDICATOR LIGHT (MIL) ISSUES

**CAMPAIGN ID #s:** P8131 & P8151

**APPLIED VEHICLE:** All 1996 I30 (CA32) California emissions vehicles registered outside of California

**Service Campaign ID #s P8131 & P8151 are no longer active.**

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID #s P8131 & P8151.
- Discard all previous versions of ITB98-036.

### AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
September 15, 1998	ITB98-036	Original bulletin published
February 15, 1999	ITB98-036a	Clarifications made in <b>INTRODUCTION</b> , and <b>SERVICE PROCEDURE</b> (steps A and F under "Water Separator Kit Installation Procedure")
August 5, 2020	ITB98-036b	Bulletin no longer active