



Preliminary Information

PIP5746 MIL Illuminated With DTC P2B95 Set In History and /or possibly DTC P2B96 P2B0A, P2B08, or P2B09

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore GX	2020	All	All	1.2 LIH	All
Chevrolet	Trailblazer	2021	All	All	1.2 LIH	All

Involved Region or Country:	North America
Condition:	MIL illuminated DTC P2B95 set in history and/or possibly DTC P2B96, P2B0A, P2B08 or P2B09
Cause:	Possible Software Anomaly

Correction

You may encounter a vehicle that has DTC P2B95, P2B96, P2B0A, P2B08 or P2B09 in history. These DTC's would only occur during a cold start.

At this time clear the trouble codes. Perform a cold restart to confirm no DTC's reset, which could indicate another issue. **You may have to allow the vehicle to sit overnight before completing the cold start verification.** If the DTC does not reset return the vehicle to the customer.

After completing the steps above If any trouble codes reset complete the published SI diagnostics for those trouble codes.

This check engine light is caused by a software anomaly which will only occur during a cold start and has no negative impact on vehicle durability or safety. Once the vehicle has warmed up it should operate normally. GM is aware of this concern and is currently working on a fix targeted for the September 2020 time frame.

Warranty Information

For vehicles repaired under the Powertrain coverage, use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation:	Description	Labor Time:
2886958	Clear DTC's and complete cold start evaluation	0.5 hr.

Version History

Version	1
Modified	08/03/2020 - Created on.



GENERAL MOTORS