



Technical Service Bulletin

Technical Service Bulletin: TSB200076	Released Date: 17-Aug-2020
INSITE™ Electronic Service Tool Cylinder Cut-out Test and Injector Performance Test Software Issue	

INSITE™ Electronic Service Tool Cylinder Cut-out Test and Injector Performance Test Software Issue

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX15 CM2250 SN

Issue

The Cylinder Cut-out Test and Injector Performance Test (IPT) in INSITE™ electronic service tool does **not** work accurately. The Cut-out Test does **not** work on the rear bank and Injector Performance Test (IPT) fails for the rear bank injectors.

Root Cause:

- Software related issue.

Resolution

- New engine control module (ECM) calibration code is released on June 2020 which will fix the Cylinder Cut-out Test and Injector Performance Test (IPT) in INSITE™ electronic service tool.
- Check ECM Calibration Revision History

- Use the recommended Cummins® electronic service tool or equivalent to find the current ECM code and revision number in the ECM.
- Compare the ECM code and revision number in the ECM to the calibration revisions listed in the ECM Calibration Revision History Database for applicable changes related to this issue.

Document History

Date	Details
2020-3-30	Module Created
2020-8-12	Update issue and resolution.

Last Modified: 17-Aug-2020
