

Steering wheel heater and/or Distronic function limited

Topic number	LI46.11-P-071594
Version	1
Function group	46.11 Steering wheel heater
Date	08-07-2020
Validity	Model series 167, 177, 205, 247, 253
Reason for change	Control unit log supplement
Reason for block	

Complaint:

Steering wheel heater and/or Distronic cannot be activated.

Cause:

Compatibility between steering wheel control panel and steering wheel electronics

Remedy:

Please do not replace any parts.

Please create a PTSS case.

For processing purposes quick test and a control unit log from the steering wheel electronics control unit ("N 135 - Steering wheel electronics (LRE)") is required.

A detailed description of the malfunction and a date or event when the problem occurred for the first time is also required.

Symptoms
Communication/information / Assistance and warning systems / Distronic / Function / Malfunction
Communication/information / Assistance and warning systems / Distronic / Display message / Function error
Chassis/suspension / Steering system / Steering wheel heater / Malfunction
Chassis/suspension / Steering system / Steering wheel heater / Cannot be switched on
Chassis/suspension / Steering system / Steering wheel heater / Insufficient heat output