AUDI DEALER COMMUNICATION

## Campaign Circular Revision – Service Action 9008 / MyAudi Software Update – USA ONLY

This notice is for:	✓Dealer Principal✓Service Manager✓Warranty Administrator✓General Manager✓Parts Manager✓Technicians✓Sales Managers✓Service Advisor✓	
Date:	September 16, 2020	
Revision Information:	The 90o8 work instructions have been revised to perform the software update using operating mode Diagnosis instead of the Flash operating mode for all models.	
	• As outlined in the work instructions, the communication path still must be changed to DoIP before starting Diagnosis. Not changing the communication path could cause failures and longer than normal flash times.	
	• Requests for additional time will be reviewed. If the diagnostic log does not indicate that the communication path was changed to DoIP, the additional time will be declined.	
	• Please see the revised 90o8 circular posted to ELSA and ServiceNet for complete information.	

-END OF MESSAGE-

Ensure all dealership personnel are aware of this notice so they are able to address customer questions. Contact Warranty if you require additional assistance. Direct press inquiries to Audi Public Relations.

udi