

## GPOP - Issue Review System

**Part Number:** 68526413A\$, 68526414A\$

**Part Description:** PUMP, Fuel Injection

---

**Issue Description:** This part requires a unique calibration to be programmed into the Engine Control Module (ECM). Failure to program the ECM with the correct calibration after installation of this pump will create an undesirable noise characteristic from the pump.

Please be sure to follow all normally published Service Bulletins, and Service Information for the latest installation instructions, and programming steps.

~  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

---

