

## **GPOP - Issue Review System**

**Part Number:** 68298380A\$

**Part Description:** LAMP, Cargo (CHMSL)

**Issue Description:** If the CHMSL is being replaced for a water leak, new screws should be used, refer to STAR parts for the latest screw PN  
Ensure the screws are tightened to 2.8 NM / 24" lbs.

~\_\_\_\_~  
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.