

GPOP - Issue Review System

Part Number: 68445817A\$

Part Description: WIRING, Front Fascia

Issue Description: For DTC codes U11E9 and/or P0073 and you confirm corrosion or water at XY101 Connector:

1. Order connector repair kits as appropriate. Meaning: no corrosion at other connectors, repair connectors using kits:
68500834AA Fascia side
68497543AA Dash Side - If more corrosion you need the whole harness.
 2. Return BOTH the female and male side of the XY101 together, please.
 3. Call *FCA Redacted Content*.
- If no response in 15 minutes, proceed with repair.

~ _____ ~
Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquiries. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

