

SSM 49157 - 2020 Escape - Illuminated MIL With DTCs U0100, U0401, P166B, P1753, P0929, And/Or P0919

Some 2020 Escape vehicles may exhibit an illuminated malfunction indicator lamp (MIL) and diagnostic trouble codes (DTCs) U0100, U0401, P166B, P1753, P0929, and/or P0919. The vehicle may also exhibit an illuminated powertrain malfunction (wrench) indicator lamp. This may be due to the software in the gear shift module (GSM). To correct the condition, reprogram the GSM using the latest software level of the appropriate Ford diagnostic scan tool. For claiming, use causal part number 7P155 and applicable labor operations in Section 10 of the Service Labor Time Standards (SLTS) Manual.

APPLICABLE VEHICLES

2020 CAR: TC CX482N ESCAPE

2020 CAR: TC CX482N ESCAPE

2020 CAR: TC CX482N ESCAPE