

SSM 49181 - 2020 Mustang GT500 - Supercharger Drive Assembly Now Serviceable Separately From Supercharger Assembly

Some 2020 Mustang GT500 vehicles may exhibit a lack of power and/or an illuminated malfunction indicator lamp (MIL) with diagnostic trouble code (DTC) P1288. If this is found to be caused by a damaged supercharger drive assembly, be aware that it is now available to service separately from the supercharger assembly. Refer to the parts catalog and Workshop Manual (WSM), Section 303-12.

APPLICABLE VEHICLES
2020 CAR: ZG S550N MUSTANG