

SSM 49196 - 2020 Explorer - Front Row Seat Side Trim Panels Loose And/Or Seat Cover Appears To Be Cut Short

Some 2020 Explorer vehicles may exhibit loose fitting side trim panels on the front row lower seat cushions and upper seat backs. This may cause the seat cover to appear to be cut improperly. The seat cover should not be replaced for this concern. Adjust the seat side trim panels for proper fit.

APPLICABLE VEHICLES
2020 CAR: TW U625N EXPLORER