

SERVICE POLICY LETTER

Reference number:	SPL-31-1435	Issued: 30 September, 2020
Subject:	Incorrect Part Information for the Secondary Door Seals	
Model(s):	DBX	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Policy Letter

Aston Martin has found an issue where the part information for the secondary seals for the doors for DBX is incorrect.

*Note: If you need the secondary seals for the left-side doors, order the secondary seal for the right-side doors.
If you need the secondary seals for the right-side doors, order the secondary seal for the left-side doors.*

Part Data

Description	Part Number	Installation Method
Secondary Seal, Front, RH	MY83-20324-AB	Install to the front left-side door
Secondary Seal, Front, LH	MY83-20325-AB	Install to the front right-side door
Secondary Seal, Rear, RH	MY83-20732-AB	Install to the rear left-side door
Secondary Seal, Rear, LH	MY83-20733-AB	Install to the rear right-side door

If you have any questions about this Policy Letter, please speak to Client Services - Technical on Tel: +44 (0) 1926 644720.

Thank you for your continued support.

Yours faithfully



Andrew West
Director, Client Services.