



Technical Service Bulletin

PSS 90 Instrument cluster clock and trip odometer reset to midnight or zero

90 20 71 2060249/2 September 30, 2020. Supersedes Technical Service Bulletin Group 90 number 20-61 dated July 17, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2021	All	FPK

Condition

REVISION HISTORY		
Revision	Date	Purpose
2	-	Revised header (Updated vehicles)
1	07/17/2020	Initial publication

Customer states:

The clock and trip odometer sporadically reset to midnight or "0.00" (Figure 1).



Figure 1. The clock and trip odometer reset to 0.

Technical Background

A shutdown issue leads to the cluster resetting itself sporadically.



Technical Service Bulletin

Production Solution

This bulletin will be updated when more information is available.

Service

1. Explain to the customer that a solution is forthcoming for the 3rd quarter of 2021 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links* >> *Service*), or through the Technical Assistance page in Elsa.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2060249) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.