

Spare Parts Requirements for Drive Motor on Front/Rear Axle - Updating Software Version (148/20)

Model Line: **Taycan (Y1A)**

Model Year: **As of 2020**

Subject: **Spare parts requirements for**

- Drive motor for electric drive on front axle (complete)
- Drive motor for electric drive on rear axle (complete)

Information: **If one of the components specified above needs to be replaced, a software update to the currently approved VR release must be performed after installing the component in the vehicle.**

Remedial Action: **Update software version as described in workshop campaign WLG2, see ⇒ *Technical Information 'WLG200 WLG2 Workshop campaign - Updating software for various control units'*.**



Information

The software version **MUST** be updated even if the workshop campaign has already been carried out. Otherwise, the functionality of the vehicle cannot be guaranteed because different software versions are installed.

Parts Info: **Overview of affected components:**

Part No.	Designation
9J1901131x	Drive motor for electric drive on front axle (complete)
9J1901141x	Drive motor for electric drive on rear axle (complete)

Invoicing

Invoicing: For documentation and warranty invoicing, enter the PQIS coding specified below in the warranty claim:

Location (FES5)	37350	Automatic transmission
Damage type (SA4)	9735	Repair in accordance with PAG instructions

References: ⇒ *Technical Information 'WLG200 WLG2 Workshop campaign - Updating software for various control units'*

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.

© 2020 Porsche Cars North America, Inc.