

## TECHNICAL TOPICS POWERTRAIN



Hybrid System Warning- Power Supply Distribution Box	19/20MY I-PACE, 20MY Range Rover & RR Sport PHEV
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>There is a “Hybrid System Malfunction” warning on the instrument cluster.</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>B1479-72 is stored in the GWM for PSDB-Actuator Stuck Open.</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>Follow TOPIx &amp; PATHFINDER Guided Diagnostics for guidance.</li> <li>Check the PSDB for electrical concerns. (short circuit, open circuit, high resistance)</li> <li>New guided diagnostic have been released for PSDB concerns. Please ensure the guided flow is followed and session included in any submissions to LTS.</li> <li>Should a replacement PSDB be necessary, please raise an EPQR with the part number of the original PSDB and your parts manager mailing information. Engineering is still looking to get parts back for analysis.</li> </ul>	

