

McLaren Senna – Removal of Engine Floor Panel Foam Padding

Bulletin type:	Service Campaign
Reference number:	SCB15 K 001
Attention:	Retailer Service Managers and Retailer Technicians
Affected vehicles:	McLaren Senna
Situation:	Potential for fuel tank corrosion due to stagnant water presence on the foam padding attached to the engine floor panel
Procedure:	Action affected vehicles during next Retailer visit. Please refer to the information outlined in this document to remove the foam padding on the engine floor panel
Date:	19 th March 2020

This Service Campaign Bulletin will cover:

1. Overview
2. Procedure
3. Warranty Information
4. Affected Vehicles

1. Overview

Through continuous product quality monitoring, it has been identified that McLaren Senna vehicles may have the potential for stagnant water build up on the engine floor panel. Therefore, the foam padding on the engine floor panel must be removed to prevent water retention and increase airflow in this area to dissipate any stagnant water around the fuel tank.

2. Procedure

To carry out the required work:

- Remove the engine floor panel
- Remove the foam padding on the engine floor panel
- Clean off any residual adhesive
- Re-Install the engine floor panel

Please refer to EA-RM-01A004-02-001 - Remove/Install Floor Panel - Engine in SIS.

CARE POINT: In the unlikely event that signs of corrosion are present on the fuel tank, please submit a TR including pictures of the concerned area to the Technical Support team for further guidance

CARE POINT: The work instruction and time allowed may differ from those published in SIS. Always follow the campaign document(s) when completing this work

3. Warranty Information

Submit a claim to the McLaren Warranty department following completion of the work, using the following details.

Description	Repair Time
McLaren Senna – Removal of Engine Floor Panel Foam Padding	0.65 hours

4. Affected Vehicles

All McLaren Senna vehicles are required to be actioned.

Your Regional Aftersales Manager will contact you with the VIN list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

Best regards,

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle.