



Preliminary Information

PIT5777 False Check Reverse Lamps Message On DIC / No DTCs

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Tahoe	2021	All	All	All	All
Chevrolet	Suburban	2021	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a Check Reverse Lamp message on the DIC. The reverse lights will still be operational and there will be no DTC's.
Cause	This concern could be caused by a calibration issue with the K219 Lighting Control Module.

Correction:

Engineering is working on new K219 Lighting Control Module calibrations. In the meantime, if no high resistance issues are found in the reverse light circuits, and the reverse lights operate, then ask the customer to dismiss/ignore the message. A new calibration should be released shortly.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
*2086138	PIT5777 - Includes Scanning for DTC, Checking Reverse light connections and operation	0.3 Hrs.
*This is a unique Labor Operation for Bulletin use only.		

Additional SI Keywords

back up backup bulb light lights

Version History

Version	1
Modified	09/18/2020 - Created on.



GENERAL MOTORS