



Preliminary Information

PIT5780 Replacement K160 BSCM P/N 84846989 and 84846988 Not Allowing Over The Air Updates (Replace Complete A104 Master Cylinder Assembly)

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Tahoe	2021	All	All	All	All
Chevrolet	Suburban	2021	All	All	All	All
GMC	Yukon Models	2021	All	All	All	All

Involved Region or Country	North America
Condition	Currently, if only the K160 BSCM is replaced for any reason, it may prevent any future Over-The-Air (OTA) updates to the vehicle. There will be no other symptoms with the vehicle and only OTA updates will be affected.
Cause	Engineering is working on this concern.

Correction:

In the meantime, to prevent this from happening, replace the complete A104 master cylinder assembly, which includes the K160 BSCM. Engineering should have this corrected shortly and then there will be no need to replace the complete A104 master cylinder assembly. This PI will be updated when it has been corrected.

Version History

Version	1
Modified	09/24/2020 - Created on.

