

## BR167 / MFA2 Cracks In Artico Seat Cushion Cover On Front Seat

---

Topic number	LI91.18-P-071629
Version	1
Function group	91.18 Seat covers
Date	08-31-2020
Validity	BR 167 with imitation leather seat covers (Artico) BR 177, 118, 247 with imitation leather seat covers (Artico) and seat climate control (SA 401)
Reason for change	
Reason for block	

---

### Complaint:

There may be cracks in the seat cushion cover (Artico imitation leather) on the front seat.

Attachments	
File	Description
example1.jpg	Example 1
example2.jpg	Example 2
example3.jpg	Example 3

### Cause:

If this complaint occurs, open a PTSS case with the following information:

- + Images of the seat cover
- + Images of the seat cushion padding (foam)
- + Manufacturing date of the seat cushion cover
- + Mileage
- + Seat climate control (yes/no)

### Remedy:

Under investigation.

Symptoms
Body / Seat / Seat cover / Chafed through
Body / Seat / Seat cover / Detaches

Operation numbers/damage codes				
Op. no.	Operation text	Time	Damage code	Note
			91A04 07	
			91N04 07	

# XENTRY TIPS

---

Validity		
Vehicle	Engine	Transmission
A (177)	*	*
B (247)	*	*
CLA (118)	*	*
GLA (247)	*	*
GLB (247)	*	*
GLE (167)	*	*
GLS (167)	*	*

## Attachments

example1.jpg:



# XENTRY TIPS

---

example2.jpg:



example3.jpg:

