

SERVICE BULLETIN 581: RIGHT HEEL GUARD



Notice Information

Ref	15752
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) – September 3, 2020**TOL Ref. # 15752-SVC****SERVICE BULLETIN 581: Right Heel Guard**

Triumph has released [Service Bulletin 581](#). Internal investigations have identified the need to retighten the right hand heel guard fixings to 10 Nm as described in the procedure outlined in [Service Bulletin 581](#).

SB 581: Right Hand Side Heel Guard			
Bulletin #	Models Affected	VIN Range	Markets
581	Tiger 900 Tiger 900 GT Tiger 900 GT Pro Tiger 900 Rally Tiger 900 Rally Pro Tiger 900 GT - LRH	See Appendix A	All markets except China & Brazil

Some affected motorcycles listed in the VIN range will have been modified and repaired by Triumph prior to their release from the factory. Unmodified motorcycles can be identified by checking the 'VIN Enquiry' on www.triumphonline.net. Motorcycles in the affected VIN range found in Appendix A must be modified prior to delivery to the customer, or at the next visit to the dealership.

Consult **Triumph Online (TOL) / Service Bulletin Page** (Bulletin # 581) or the attached [Service Bulletin 581](#) PDF for additional information including Fitting, Warranty Claim and Part Ordering instructions. Please also ensure that all relevant staff are up to date on these service instructions.

Reminder: Use the **"VIN Enquiry"** function within TOL (found under the **Service / Technical** drop down menu) to search for any outstanding bulletins or recalls whenever a new motorcycle arrives or a Triumph owner visits your dealership.

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.



