



SIB 61 02 20

SERVICE ACTION: WIRING HARNESS ABRASION PROTECTION

2020-09-09

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

E-Series	Model Description
K67 (0E23)	S 1000 RR
K69 (0E43)	S 1000 XR

The affected vehicles have been marked with campaign number 0061440000

In order to determine if a specific vehicle is affected by this campaign it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

The engine wiring harness may chafe on the honeycomb structure of the frame. In case of damage to the wiring harness, the wake-up line of the instrument cluster will be damaged. The instrument cluster will no longer be activated with "Ignition ON".

CORRECTION

Inspect the wiring harness for damage and install wiring protection as detailed in the enclosed Repair Instruction "00 60 358 - Retrofitting abrasion protection for wiring harness".



PARTS INFORMATION

Part Number	Description	Quantity

46 51 7 924 378	Abrasion protection set	1
61 13 1 372 391	Cable straps	as needed

WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Motorcycles.

Defect Code:	0061440000	Converting abrasion protection for wiring harness
---------------------	------------	---

Labor Operation:	Labor Allowance:	Description:
00 60 858	3 FRU's K67 6 FRU's K69	Retrofit abrasion protection for wiring harness

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

In case of a necessary wiring harness repair, the required working time must be indicated with FRU Number 61 11 013 and work explained.

QUESTIONS REGARDING THIS BULLETIN

Technical inquires	Please contact the Motorrad Technical Support Group
Warranty inquires	Submit an IDS ticket to the Warranty Department
Parts inquires	Submit an IDS ticket to the Motorrad Parts Department

Powered by [Froala Editor](#)

Supporting Materials

[picture_as_pdf 61 02 20 SA Wiring Harness Abrasion Protection.pdf](#)